

HAMM TANDEMWALZE HD 8 VV

????? ????????????????		BILDER
ID	16986	     
??? ???????	2012	
?????????	464	
??? [?]	1,58	
?????????? ?? ??????????????	✓	
????????? ?????????? ??????	✓	
???????????? ?????????????? CE	✓	
?????		
?????????????????	Kubota	
????? [??]	D1005	
????????? ?????????? [??]	14,8	
?????????? ????????	2011 Tier4	
EPA ??????	✓	

??????????			
?????	??????	????????????	????????????
?????????? ??????	✓		
???????	✓		
Leckgas	✓		
Ansprungsverhalten	✓		
???	✓		
?????????? ????????	✓		
????????? ??????????	✓		
????? ??????????	✓		

???????????	??????	???????????	???????????
??????	✓		
?????	✓		
??????	✓		
???????	✓		
??????	✓		
????? ??????????	✓		
??????	??????	???????????	???????????
???????	✓		
???????	✓	Fahrhebel schwergängig	
????? ??????????	✓		
????????????????????	??????	???????????	???????????
???????????	✓		
???????	✓		
???????????	✓		
???????????	▲	Batterie schlecht. Pole korrodiert, sollte erneuert werden	
????? ??????????	✓		
?????	??????	???????????	
Abstreifer	80%		
Bandagengummis	70%		
??????	??????	???????????	???????????
?????????	✓		
????????? ??????	✓		
?????	✓		
???	✓		