

WIRTGEN STRAßENFRÄSEN W 2100

????? ????????????????		BILDER
ID	16935	     
??? ???????	2004	
?????????	6992	
??? [?]	34,4	
????????? ?????????? ???????	✓	
?????		
?????????????????	CAT	
?????? [???	C16	
????????? ?????????? [???	470	
?????????? ????????	TierII	
?????????? ??????? ? ????????	✓	
?????????????????		
?????????? ????????	2100	
????????? ????????????????	320	
Wechselhaltersystem	HT 11	
starres Band	✓	
?????????? ??????? ? ??????????????? [?]	2	
?????? ???????	✓	
Seilzugsensor	✓	

??????????			
?????	?????	???????????	???????????
????????? ?????	✓		
??????	✓		
Leckgas	✓		
Ansprungsverhalten	✓		
???	✓		
????????? ???????	✓		
???????? ???????????	✓		
????? ???????????	✓		
???????????	?????	???????????	???????????
??????	✓		
?????	✓		
??????	✓		
???????	✓		
??????	✓		
????? ???????????	✓		
???????	?????	???????????	???????????
???????	✓	Leicht beschädigt	
???????	✓		
???????	✓		
????? ???????????	✓		
????????????????????	?????	???????????	???????????
??????????	✓		
???????	✓		
??????????????	✓		
??????????????	✓		
????? ???????????	✓		

?????	??????	???????????	???????????
Turas	90%	Hi 100% /Vo 70%	
??????	90%	Hi 100% /Vo 70%	
Kettenbänder	90%	Hi 100% /Vo 70%	
???????	90%	Hi 100% /Vo 70%	
?????	??????	???????????	???????????
Aufnahmeband	80%		
Abwurfband	80%		
?????????? ?????	70%		
??????	??????	???????????	???????????
??????????	✓		
?????????	✓		
????????? ?????	✓		
????	✓		
???	✓		
??????	✓		